
#### Order #XXXXX SYM-412 Portable Counter

Item	Qty.	Description
	2	16.732"h aluminum Leg (lower)
	2	16.732"h aluminum Leg (lower w/ Velcro)
	2	16.732"h aluminum Leg (upper)
	2	16.732"h aluminum Leg (upper w/Velcro)
	1	43"w x 21.5"d Counter Base
	1	40.1"w x 16"d Counter Shelf
	1	43"w x 21.5"d Counter Top

#### Steps:


Note: Assemble counter upside-down.


- 1) Attach upper legs to underside of Counter Top. Twist to tighten.
- 2) Connect lower Legs through Counter Shelf to upper Legs, as shown.
- 3) Place Counter Base over lower Legs & secure with wing nuts.
  4) Turn counter unit over & affix Graphic to Velcro on front of unit.



When assembled

### Assemble unit upside-down.





Note: Velcro must face **front** of assembled counter.


# SETUP INSTRUCTIONS

### General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

### Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.



Part Identification - Numbering



**Engaged Lock** 

## Disassembly

- For loss prevention, keep all knobs & connectors attached to extrusions during disassembly.





DO NOT USE POWER TOOLS



**ALL CONNECTIONS MUST BE TIGHTLY SECURED** 



## Top View of Each Level

